


IRROMETER®

1425 PALMYRITA AVE
RIVERSIDE, CA 92507
P: 951.682.9505
E: TECHSUPPORT@IRROMETER.COM



- ① WATERSWITCH AC (WS-AC).
- ② COMMON WIRE FROM CONTROLLER.
- ③ REMOTE CONTROL VALVE OR COMMON OF MULTIPLE VALVES.
- ④ STATION VALVE WIRING FROM CONTROLLER.
- ⑤ WATERMARK MODEL 200SS SOIL MOISTURE SENSOR. INSTALL PER MANUFACTURER SPECIFICATIONS.

NOTES:

- THIS APPLICATION OVERRIDES A SINGLE VALVE OR GROUP OF VALVES FROM OVER WATERING. INSTALL SENSOR IN A DRYER AREA OF THE LAST VALVE TO RUN IN SEQUENCE (IF MULTIPLE VALVES).
- WATERSWITCH AC (WS-AC) INSTALLED AT VALVE OR AT CONTROLLER. SPLICE ADDITIONAL WIRE IF NECESSARY.

NO SCALE

WATERSWITCH AC SINGLE VALVE WIRING